

The following tables list the software issues that are fixed in this release. The **P** column indicates the priority of the software fix, as follows:

- 0 = Critical
- 1 = Major
- 2 = Medium
- 3 = Minor

The tables are sorted first by Category, then by Priority (P), then by Bug ID.

Software Fixes in NetIron Patch Release 09.4.00b

Category	Ρ	Description	Bug ID #
VRRP	1	Module: N/A	31540
		Symptom: In a Router configured with VRRP/VRRP-E, configuring the priority for a backup VRID but not configuring the mode can cause a system reset.	
		Resolution: Fixed in this release	
VRRP	2	Module: N/A	47830
		Symptom: In a Router configured with VRRP-E, using the same VRID on multiple interfaces can cause corruption of the internal VRRP-E data structure, which can cause failure when configuring additional VRIDs.	
		Resolution: Fixed in this release	
Hotswap	1	Module: N/A	57475
		Symptom: In a Switch or Router, hot swapping a module can sometimes cause system reset.	
		Resolution: Fixed in this release	
IP Stack	1	Module: N/A	58732
		Symptom: In a Switch or Router, forwarding of broadcast packets can occasionally cause system reset.	
		Resolution: Fixed in this release	
MRP	1	Module: N/A	75863
		Symptom: The output of the show metro command indicates the wrong interface type for ring interfaces. For example, the descriptor for a regular port is "Tunnel" and the descriptor for a tunnel port is	

Category	Ρ	Description	Bug ID #
		"Regular".	
		Resolution: Fixed in this release	
BGP	1	Module: N/A	76964
		Symptom: In a Router configured with IBGP and static routes, the static route is installed in the IP Route table incorrectly, preferring the static route over the IBGP route even though the static route has a lower admin cost.	
		Resolution: Fixed in this release	
System	2	Module: N/A	77987
		Symptom: In a Router, accessing a corrupted internal port data structure can cause a system reset.	
		Resolution: Fixed in this release	
System	2 Module: N/A		37424
		Symptom: In a Switch or Router, sometimes a corrupted port number when used to access internal data structure can cause a system reset.	
		Resolution: Fixed in this release	
System	2	Module: N/A	82608
		Symptom: The activity LED does not correctly show the traffic status in a Switch or Router with 10Gig Xenpak module using ER optics.	
		Resolution: Fixed in this release	

Software Fixes in NetIron Patch Release 09.4.00a

Category	Ρ	Description	Bug ID #
L2 Trace	1	Module: N/A	75897
		Symptom: In a Router configured with route-only on a virtual routing interface, any L2 Trace packet received is incorrectly forwarded to the VLAN associated with the virtual routing interface.	
		Resolution: Fixed in this release.	
System	1	Module: N/A	37620
		Symptom: In a Switch or Router, the port data structure is sometimes corrupted. This can cause a system reset.	
		Resolution: Fixed in this release.	
System	1	Module: J-BxGRM4	47846
		Symptom: In a Switch or Router, sometimes the following error message is seen on the console * * * * INCORRECT index [0000a468] for get_global_mask * * * *	
		Resolution: Fixed in this release.	

Category	Ρ	Description	Bug ID #
System	1	Module: N/A	51387
		Symptom: In a Switch or Router, reloading the management module can occasionally cause a system reset.	
		Resolution: Fixed in this release.	
System	1	Module: N/A	59885
		Symptom: In a Switch or Router, occasionally there is a memory	
		leak when running SNMP.	
		Resolution: Fixed in this release. The memory can now be tracked. This can be enabled by turning it on, and displaying the memory resource using following commands: dm mem-leak show size dm mem-leak [on off]	
System	1	Module: N/A	73223
		Symptom: In a Router, the age in an ARP entry is incorrectly refreshed when used in sending traffic to a destination address.	
		Resolution: Fixed in this release.	
VRRP	1	Module: N/A	71983
		Symptom: In a Router configured with VRRP and VRID assigned with multiple Virtual IP addresses, if the owner VRRP router transitions from Master to Backup, the interface routes associated with secondary Virtual IP address are present in the Routing table after the transition.	
		Resolution: Fixed in this release.	