


TBS



SILART
8 800 555 09 66
E-mail: info@silart.com
Web: www.silart.com



	TBS-140		TBS-240		TBS-160		TBS-260	
	NC	NO	NC	NO	NC	NO	NC	NO
	-20...+40 °C				0...+60 °C			
	7±3 °C							
	±4 °C							
()	250VAC / 16 (cos =0,95)							
()	72VDC / 30							
AC/DC	10 / 5							
	1500							
	50							
	10							
/	-40...+80 °C							
16 (cos =0,95)	100000							
	IP20							
	UL94 V-0							
	RAL7035							
	0,35...2,5 ²							
	* 0,35...1,5 ²							
	2,5		0,4					
	36							

*- (. . .4.)

5.	
	+5° NC -
	T = 5°C + (7+3)°C + 4°C = 19°C
T	-
5°C -	
(7+3)°C -	
4°C -	
	+20° NO -
	T = 20°C + (7+3)°C + 4°C = 34°C
	5...10°C.

1.

(. . .1);

2.

TBS

- NC ():
- NO ():

4.

35 DIN -

5

3.

14 ;

3

4-

