

Cisco ASA 5585-X I/O Modules

PB711904

Cisco ASA 5585-X I/O Modules provide high interface-density to mission-critical data centers that require exceptional flexibility and security. With two 8-port 10 Gigabit Ethernet modules and one Security Services Processor (SSP)-40 or SSP-60 module, Cisco ASA 5585-X can support up to 20 10 Gigabit Ethernet ports in 2 rack unit (2RU) chassis. With two 20-port 1 Gigabit Ethernet modules and one SSP module, Cisco ASA 5585-X can support up to 50 1 Gigabit Ethernet ports in 2RU chassis.

The I/O modules go into the top slot of the Cisco ASA 5585-X chassis. The Cisco ASA 5585-X Divider divides the top slot into two half-slots, and each I/O module occupies one half-slot. All the ports on the 10 Gigabit Ethernet modules are dual Small Form-Factor Pluggable or Small Form-Factor Pluggable Plus (SFP/SFP+) ports that support both 1 Gigabit Ethernet SFPs and 10 Gigabit Ethernet SFP+ modules. The 1 Gigabit Ethernet module supports 8 10/100/1000 Base-T ports and 12 SFP ports for high-fiber density. Table 1 describes the different Cisco ASA 5585-X I/O Modules available.

Table 1. Cisco ASA 5585-X I/O Modules

Product Description	Number of Ports			Product ID
	SFP/SFP+ Ports	SFP ports	10/100/1000 Base-T ports	
Configuration Options				
Cisco ASA 5585-X 8-port 10 Gigabit Ethernet Module	8	-	-	ASA5585-NM-8-10GE
Cisco ASA 5585-X 4-port 10 Gigabit Ethernet Module	4	-	-	ASA5585-NM-4-10GE
Cisco ASA 5585-X 20-port 1 Gigabit Ethernet Module	-	12	8	ASA5585-NM-20-1GE
Cisco ASA 5585-X Slot Divider	-	-	-	ASA5585-SEPTUM
Cisco ASA 5585-X Half-Slot Cover	-	-	-	ASA5585-BLANK-H
Spares				
Cisco ASA 5585-X 8-port 10 Gigabit Ethernet Module	8	-	-	ASA5585-NM-8-10GE=
Cisco ASA 5585-X 4-port 10 Gigabit Ethernet Module	4	-	-	ASA5585-NM-4-10GE=
Cisco ASA 5585-X 20-port 1 Gigabit Ethernet Module	-	12	8	ASA5585-NM-20-1GE=
Cisco ASA 5585-X Slot Divider	-	-	-	ASA5585-SEPTUM=
Cisco ASA 5585-X Half-Slot Cover	-	-	-	ASA5585-BLANK-H=

When only one I/O module is installed in the top slot of the ASA 5585-X chassis, a half-slot blank cover is required to cover the empty half-slot. Minimum software required is Cisco ASA Software Version 8.4.4.

The Cisco ASA 5585-X IO modules are orderable and shipping.

Table 2 lists the 10 Gigabit Ethernet SFP+ and 1 Gigabit Ethernet SFPs that are supported.

Table 2. SFPs and SFP+ Modules Supported

	Product ID	Product Description
SFP+ Modules Supported	SFP-10G-SR	10G SR SFP+ modules
	SFP-10G-LRM	10G LRM SFP+ module
	SFP-10G-LR	10G LR SFP+ module
	SFP-10G-ER	10G ER SFP+ module
	SFP-H10GB-CU1M	10G BASE-CU SFP+ cable 1 meter, passive
	SFP-H10GB-CU3M	10G BASE-CU SFP+ cable 3 meter, passive
	SFP-H10GB-CU5M	10G BASE-CU SFP+ cable 5 meter, passive
	SFP-H10GB-ACU7M	10G BASE-CU SFP+ cable 7 meter, active
	SFP-H10GB-ACU10M	10G BASE-CU SFP+ cable 10 meter, active
SFP Modules Supported	GLC-SX-MMD	Cisco 1000 Base-SX SFP module, MMF, 850nm, DOM
	GLC-LH-SMD	Cisco 1000 Base-LX/LH SFP module, MMF/SMF, 1310nm, DOM
	GLC-T	Cisco 1000 Base-T copper SFP
	GLC-ZX-SMD	Cisco 1000 Base-EX SFP module, SMF, 1550nm, DOM
	GLC-EX-SMD	Cisco 1000 Base-ZX SFP module, SMF, 1310nm, DOM

Additional Information

For more information, visit: <http://www.cisco.com/go/asa>



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)